

## IECEX Quality Assessment Report: US/UL/QAR14.0015/02 details

| QAR :   |  |           |                |        |                                 |  |   |   |  |   |  |  |   |
|---|--|-----------|----------------|--------|---------------------------------|--|---|---|--|---|--|--|---|
| QAR Reference Number*:<br>(automatic numbering)             | US/UL/QAR14.0015/02  |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Related QARs:   | <a href="#">US/UL/QAR14.0015/01</a><br><a href="#">US/UL/QAR14.0015/00</a>   |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Status*:  | Issued   |           |                |        |                                 |  |   |   |  |   |  |  |   |
| QAR Free Reference Number*:                                 | 4787343203   |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Audit Date*:<br>(yyyy-mm-dd)                                | 2016-02-24   |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Date of Issue*:<br>(yyyy-mm-dd)                             | 2016-04-22   |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Details of change*:   | Reassessment Audit   |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Valid until*:<br>(yyyy-mm-dd)                               | 2019-04-24   |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Site(s) audited*:   | Pulsafeeder Inc.<br>2883 Brighton Henrietta Town Line Road<br>Rochester, NY 14623<br>USA   |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Issuing ExCB*:  | UL - UL LLC  |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Manufacturer*:  | Pulsafeeder Inc.<br>2883 Brighton Henrietta Town Line Road<br>Rochester, NY 14623  |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Country of Manufacture*:                                    | United States of America   |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Product information*:                                       | Pump Controllers and Pressure Switches   |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Protection concept*:  | Flameproof "d"<br>Equipment dust ignition protection by enclosure "t"  |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Related IECEX Certificates:<br>(automatic linking)          |  |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Related Certificates:<br>(manual insertion)                 |  |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Related IECEX Certificates<br>for previous versions:        |  |           |                |        |                                 |  |   |   |  |   |  |  |   |
|   | <table border="1"> <thead> <tr> <th>ExCB name</th> <th>CoC and Status</th> <th>Totals</th> </tr> </thead> <tbody> <tr> <td><input type="checkbox"/> UL LLC</td> <td><a href="#">IECEX UL 14.0118X issue: 1 [Current]</a></td> <td>1</td> </tr> <tr> <td><input type="checkbox"/> Underwriters Laboratories Inc (UL)</td> <td><a href="#">IECEX UL 14.0118X issue: 0 [Current]</a><br/><a href="#">IECEX UL 14.0055X issue: 0 [Current]</a></td> <td>2</td> </tr> <tr> <td></td> <td></td> <td>3</td> </tr> </tbody> </table> | ExCB name | CoC and Status | Totals | <input type="checkbox"/> UL LLC | <a href="#">IECEX UL 14.0118X issue: 1 [Current]</a> | 1 | <input type="checkbox"/> Underwriters Laboratories Inc (UL) | <a href="#">IECEX UL 14.0118X issue: 0 [Current]</a><br><a href="#">IECEX UL 14.0055X issue: 0 [Current]</a> | 2 |  |  | 3 |
| ExCB name   | CoC and Status   | Totals    |                |        |                                 |  |   |   |  |   |  |  |   |
| <input type="checkbox"/> UL LLC                             | <a href="#">IECEX UL 14.0118X issue: 1 [Current]</a>   | 1         |                |        |                                 |  |   |   |  |   |  |  |   |
| <input type="checkbox"/> Underwriters Laboratories Inc (UL) | <a href="#">IECEX UL 14.0118X issue: 0 [Current]</a><br><a href="#">IECEX UL 14.0055X issue: 0 [Current]</a>   | 2         |                |        |                                 |  |   |   |  |   |  |  |   |
|   |  | 3         |                |        |                                 |  |   |   |  |   |  |  |   |
| Comment:  |  |           |                |        |                                 |  |   |   |  |   |  |  |   |
| Attachment:   |  |           |                |        |                                 |  |   |   |  |   |  |  |   |

---

Last modified: 04/23/2016 06:01:07 AM

Copyright © IEC-IECEX 2016 , Geneva, Switzerland. All rights reserved.