



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.: **US/UL/QAR14.0015/05** Page 1 of 1

QAR Free Ref. No.: **4789648876** Status: **Issued**

Details of change: **Surveillance Audit** Date of issue: **2020-10-28**

Site(s) audited: **Pulsafeeder Inc.** Valid until: **2022-04-24**  
2883 Brighton Henrietta Town Line Rd  
Rochester, NY 14623  
**United States of America** Audit date: **2020-10-08**

Issuing ExCB: **UL - UL LLC**

Manufacturer: **Pulsafeeder Inc.**  
2883 Brighton Henrietta Town Line Road  
Rochester, NY 14623

Location of Manufacturer: **United States of America**

Product information: **Pump Controllers and Pressure Switches**

Protection concept: **Flameproof "d" Non-Electrical "h" Dust Ignition Protection by Enclosure "t"**

Related QARs:

<a href="#">US/UL/QAR14.0015/00</a>	<a href="#">US/UL/QAR14.0015/01</a>	<a href="#">US/UL/QAR14.0015/02</a>
<a href="#">US/UL/QAR14.0015/03</a>	<a href="#">US/UL/QAR14.0015/04</a>	

Related Certificates (manual insertion):

Related Certificates (automatic linking):

Related Certificates for previous versions:

<a href="#">IECEX ETL 18.0040X issue: 0</a>	<a href="#">IECEX ETL 18.0040X issue: 1</a>	<a href="#">IECEX UL 14.0055X issue: 0</a>
<a href="#">IECEX UL 14.0118X issue: 0</a>	<a href="#">IECEX UL 14.0118X issue: 1</a>	<a href="#">IECEX UL 14.0118X issue: 2</a>
<a href="#">IECEX UL 14.0118X issue: 3</a>	<a href="#">IECEX UL 14.0118X issue: 4</a>	

Comments: